

SUNDRY NOTICES AND REPORTS ON WELLS

Well No. 1 is locate NW/4 Sec. 17 (% Sec. and Sec. No.) Allison Penn.	d 554 ft. fr 9–5 (Twp.) Lea	(D)	1 7 1	ي. (بي) - ا
NW/4 Sec. 17	9-5	37-E	nd 554 ft. from	line of 3604. 17
		(D)	1 7 1	1. The second
			June 3	EIVE TO 6
	ABOVE BY CHECK M	TARK NATORE OF REPO		
			RT, NOTICE, OR OTHER DATA)	
NOTICE OF INTENTION TO PULL OR AL NOTICE OF INTENTION TO ABANDON W			ITARY WELL HISTORY	
NOTICE OF INTENTION TO SHOOT OR			IT REPORT OF ABANDONMENT.	
NOTICE OF INTENTION TO RE-DRILL OF	R REPAIR WELL	SUBSEQUEN	IT REPORT OF RE-DRILLING O	
NOTICE OF INTENTION TO TEST WATER	₹ SHUT-OFF	SUBSEQUEN	IT REPORT OF ALTERING CASH	NG
				CIDIZING
NOTICE OF INTENTION TO DRILL.			NT REPORT OF WATER SHUT-ON IT REPORT OF SHOOTING OR A	

The elevation of the derrick floor above sea level is 4025 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged and abandoned as follows: Recovered 6097' of 8-5/8" casing and 1600' of 8-5/8" casing of original 4275' of 8-5/8" and 9785' of 5½" casing run; spotted 50 ax cement over 5½" cas. perforations at 9728-9732; set 25 ax cement in and out of 5½" casing stub; set 100' of cement in base of 8-5/8" casing at 4275'; 50 ax cement set in top of 8-5/8" casing at 2675'. Set 100' cement plug in base of 13-3/8" casing at 365', and set 20 ax cement in top of 13-3/8" casing with proper U.S.G.S. marker installed. Hole filled with heavy mud between plugs. Location cleaned up, junk removed, pits leveled, ready for inspection.

Verbal permission to plug as above obtained from Mr. Standley in March, 1963.

Arnold H. Bruner	by the Geological Survey before operations may be commenced.
C/o J. N. Sikes, Jr.	$O \cap A^{-}$
121 Vaughn Bldg.	By
Midland, Texas	Agent Title
	Arnold H. Bruner C/o J. N. Sikes, Jr. 121 Vaughn Bldg.

GPO 914974

GENERAL DO U.C.C.