(Form,C-103) (Revised 7/1/52)\*

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

In	dicat	e Nature	of	Report	by	<b>Checking Below</b>	w
----	-------	----------	----	--------	----	-----------------------	---

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	X	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)	

## September 17, 1957 P. C. Bex 1797, Midland, Texas

Following is a report on the work done and the results obtained under the heading noted above at the

Karry Base Drilling Ge. A Chanplin Gil & Rafin (Company or Operator)	dng. Co. State #A# (Lease)
(Contractor)	., Well No1
T 108, R. 378, NMPM., Bahol Devenian	
The Dates of this work were as folows:	
Notice of intention to do the work (was) (with the submitted on Form	C-102 on
and approval of the proposed plan (was) (proposed plan (was)	
DETAILED ACCOUNT OF WORK	DONE AND RESULTS OBTAINED

The State "A" No. 1 Well was plugged according to the rules and regulations stipulated by the New Maxico Gil Conservation Commission. The following procedure was followed in plugging this well:

- 1. The 5-1/2" production easing string was cut off at 4,930 feet and 149 joints of easing were salvaged.
- 2. A 25 suck commt plug was placed in 5-1/2" casing from 9,038 feet to 9,260 feet.
- 3. A 50 seek eccent plug was placed at the bottom of 8-5/8" intermediate easing from 4,039 feet to 4,198 feet.
- 4. A 20 each coment plug was placed at the top of 8-5/8" casing.

## The well was full of 9.5 pound/gallon phosphate base mud at the start of the plugging operations

Witnessed by	1.4. Refining Con District Superintendent Company) (Title)
Approved: OIL CONSERVATION COMMISSION	I hereby certify that the information given above is true and complete to the best of my knowledge. Name. 7.97. Brown
(Name) (Title) (Date)	PositionDigtrigt Superintendent Representing

.

and the second second

1. (\* **-** 1.) (\* ) · And App

د. الالاحة الجمعية 2008، يتعليم معلمة من المالي وعلم المعلم منها الإيلام مناكرة في المستخدم المعادية. - المثلث من منذ في المالي المعلم الفي المعادية. - المعادية المعادية المعادية المعادية من المعادية من المعادية والأكامة معادية من المناكرة في - المعادية المعادية المعادية المعادية المعادية من الأعلم والمعادية من المعادية من المعادية المعادية المعادية ال - المعادية المعادية المعادية المعادية المعادية من الأعلم المعادية المعادية المعادية المعادية المعادية المعادية المعادية - المعادية المعادية المعادية المعادية المعادية المعادية من الأعلم والمعادية من المعادية المعادية المعادية المع

a service de la service d

e de la construcción de la constru