

Below is listed the results of Drill Stem Test, conducted on the Champlan Refining Company and Harry W. Bass Drilling Company State A # 1 NM, Echo Field, Lea County, New Mexico.

DST - 9250 to 9410 Open 2 hours and 30 minutes. Recovered 230 slight oil and gas cut mud.

DST - 9400 to 9440 Open 20 minutes. Recovered 25' drilling mud.

DST - 10039 to 10090 Open 1½ hours. Recovered 100' salt water cut mud and 1100' salt water.

DST - 11634 to 11675 Open 3 hours and 15 minutes. Recovered 1080' water blanket cut with oil and gas + 1710', oil + 900' very heavy oil and gas cut mud. Flowing 1493 # 15 minutes shut-in 4592 Hydrostatic pressure 5910#.

DST - 11675 to 11700 Open 105 minutes. Recovered 1000' water blanket + 1000' mud.

DST - 11685 to 11725 Open 30 minutes. Recovered 1000' water blanket + 30 feet mud.

no documents, and all other information are...
... ..

... ..

... ..

... ..

... ..

... ..

... ..