

Form 9-281a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 067891

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 23, 1956

U.S.A. (New Mexico) "B"  
Well No. 1 is located 660 ft. from XX line and 1980 ft. from EW line of sec. 5  
SE/4 SW/4 5 9-S 38-E NMPM  
(Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3976 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The hole was loaded with 7.7 mud.  
A 25 sx cement plug was spotted from 11645'-11566'.  
A 75 sx cement plug was spotted from 9020 - 8784'.  
A 35 sx cement plug was spotted at bottom of 8-5/8" casing (4175 - 4072').  
A 15 sx cement plug was spotted at surface with a 4" pipe marker properly stamped.  
Location is ready for inspection.

1-10 50 Sec. 60 100 3 100 100

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Texas Pacific Coal & Oil Company  
Address P. O. Box 1688  
Hobbs, New Mexico

By Arthur M. Smith  
Title District Engineer