

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 04752

Unit U. S. GEOLOGICAL SURVEY

RECEIVED

DEC 30 1946

ROSWELL, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 30, 1946

Well No. 1 is located 640 ft. from N line and 305 ft. from W line of sec. 29
Range 30E, Twp. 9S, R. 38E, N.M.P.M.
 (4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox, Lin County, New Mexico.
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3967 ft. (Gr.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well is running approximately the same as the nearest well three miles southwest.

We are requesting a change in plan of drilling in. Instead of running 7" O.D. casing we will drill the well in by casing, have the screen installed, and run Schlumberger, submitting a complete report to the U.S. Geological Survey office at Roswell. If the reports indicate that we have a well 7" O.D. casing will be run and cemented with enough cement to bring it to the base of the salt.

Present depth is 4150 feet at 4:00 p.m., December 29, 1946. 7" casing will be set at or near the top of the pay section.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Devonian Oil Company

Address Box 1379
Tulsa, Oklahoma

By F. H. Wolfe
 Superintendent
 Title _____