Form 9-331 a. (Feb. 1961)		Budget Bursau No. 42-R368.4. Approval expires 12-31-60. Senta Po Land Office		
	(SUBMIT IN TRIPLICATE)	Land Office SHI HOBBS OFFICE 0. C. C.		
	UNITED STATES	Nou C in		
	DEPARTMENT OF THE INTERIOR	Unit		
	GEOLOGICAL SURVEY			

....

SUNDRY NOTICES AND REPORTS ON WELLS

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT; NOTICE, OR OTHER DATA)							
	í						
	() () () () () () () () () ()						
	1						
SUBSEQUENT REPORT OF WATER SHUT-OFF							
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY.						

				·····, 1/ ···· ··
Bell-Federal Well No. 1 is locate	d 1980 ft.	from $\left\{ \begin{matrix} N \\ \blacksquare \end{matrix} \right\}$ line as	nd 1980 ft. from	$\begin{bmatrix} \mathbf{E} \\ \mathbf{x} \end{bmatrix}$ line of sec. 20
SW/4 NE/4 Sec. 20	9 8 (Twp.)	38E (Range)	(Meridian)	
Smy er - San Andres		Lee ounty or Subdivision)		te or Territory)

The elevation of the derrick floor above sea level is 3963. ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cleaned out eld Warren Petroleum well to 5127 .

Ran 55" J-55, 14# liner to 5098', top of liner 4295'. Cemented with 155 sacks Pommix and 35 sacks latex. Top of ement 4250'. Ran Gamma Ray-Neutron to 5071'. Perforated the following intervals - 2 shots per foot: 4910-14', 4926-36', 4951-71'. Ran 2" tubing with packer set at 4800' and attempted to treat with 1000 gallens mud acid. Packer failed. Reversed acid out. Pulled tubing and reren tubing with packer set at 4800'. Treated all perfs with 1000 gallons mud acid. Maximum pressure 2000#. Swabbed well, tested gas TSTM plus small amount of eil and acid water. Treated all perfs with 7000 gallens 15% acid. Maximum pressure 3300#. Shut down pressure 1700#. Swabbed, well kicked off. Elowdown ggauge 365 mefpd from all somes. Pulled tubing and packers. Reren tubing with straddle packers. Swabbed upper

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Alamo Corporation

Address 2010 34th Street

Lubbeck, Texas

By Lleyd Winderson_ Lloyd Henderson

Title Gaologist

(Over)

sone 4951-71'. Well tested 52 merfod plus oil and water (not gauged). Strattled perforations 4910-14; swabbed, tested 275 mcfpd with small amounts of water, edl and mud. Straddled perfs 4920-36. Swabbed, tested estimated 50 mcfpd plus some oil and water. Released packers, well tested estimated 500 mcfpd from all perfs. Pulled tubing and packers. Perforated 4902-08' with 12 shots total. Ran tubing with straddle packers, treated perforations 4902-08' and 4910-14' with 6000 gallons regular acid. Swabbed 48 hours. Shut in 30 minutes. Blowdown 350 mcfpd. Reset packers opposite 4926-36' perforations and attempted to treat with 5500 gallons regular acid. Perforations were either communicated with upper perfs or packers failed. Reversed out acid. Pulled tubing and packers. Treated perfs 4951-71 with 5500 gallons. Treatment communicated with other sones. Swabbed all sones. Well kicked off and tested estimated 360 mcfpd plus 33 bbls. fluid, 80% water. Cleaned well on 7 day blow down. Well tested 550 mcfpd through .2180" orfice. Tubing pressure 537#.

LOG TOPS: San Andres 4183 (-216) San Andres Porosity 4892' (-927)