


(SUBMIT IN TRIPLICATE)

Land Office _____

Lease No. 06519UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Results of remedial job.

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 660 ft. from N line and 660 ft. from W line of sec. 24

Northwestern Federal
1 (1/4 Sec. and Sec. No.) T 23 N - 38 E (Twp.) (Range) (Meridian)
Weyer Gas (Field) Lea (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3924 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforated upper sand section from 4915 - 4931 w/5 - 5/8 jet shots. Ann circulate
ladder treated w/200 gals. and acid, followed w/200 gals. regular acid,
sat 1 hour for acid to work. Swabbed back well. Tested at rate of
1,250, 10. 41 bbl., 25 bbls. water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Western Drilling Co., Inc.Address Box 1392Albuquerque, N.M.By J. D. HendersonTitle Superintendent