

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Cabeen Exploration Corporation		Address 1502-211 N. Ervay, Dallas, Texas				
Lease State	Well No. 1	Unit Letter 6	Section 7	Township 11-S	Range 38-E	
Date Work Performed September 14, 1963	Pool Undesignated			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☒ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well plugged as follows: A 25 sack cement plug was spotted at interval 4970-5050. A 20 sack plug was spotted at interval 4300-4360. A 25 sack plug was placed in bottom of 8 5/8" surface casing. A 10 sack plug was placed at surface cementing in a six foot 4 inch marker with cap. Location was cleared of all debris, pits filled. Casing left in well is 8 5/8" surface casing set at depth of 4344.

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge. <i>Paul G. White</i>	
Approved by		Name Paul G. White	
Title		Position Consulting Engineer	
Date		Company Cabeen Exploration Corporation	