



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM 0459
Unit Federal Kelly "A"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 14, 19 63

Well No. 2 is located 1980 ft. from N line and 1980 ft. from E line of sec. 19
NE/4 Sec. 19 9-S 38-E NMPH
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Smyer San Andres Lee New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded at 10:00 PM 1-9-63. Cactus Drilling Corporation-contractor.

Cemented 423' of 7-5/8" OD Casing at 423' with 250 sks cement & 2% chl. chl. Completed at 10:00 AM 1-10-63. Cement circulated to surface. WOC.

1-11-63 Tested casing w/2000 lbs pressure for 30 mins before and after drilling out - tested ok, no decrease in pressure. Cement set 24 hrs prior to drilling out.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sinclair Oil & Gas Company

Address 520 E Broadway

Hobbs, N.M.

By

Title Dist. Supt.

Originals: USGS-Hobbs; cc:MFD, JM, File