

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Southland Royalty Company		J. D. Guye
3. Address of Operator		9. Well No.
1405 Wilco Bldg., Midland, Texas 79701		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>north</u> LINE AND <u>660</u> FEET FROM		Inbe (Permo-Penn.)
THE <u>east</u> LINE, SECTION <u>12</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4199.3' GR		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Moved in Western Casing Pullers on 4-14-70. Set bridge plug on wire line @ 9200'. Spotted 2 sx cement on top of bridge plug. Spotted 25 sx cement 4132-4220'. Recovered 4220' of 5 1/2" casing. Spotted 25 sx cement @ 3962-4050' (bottom of 9 5/8" casing @ 4000'). Spotted 25 sacks cement @ 1632-1668'. Recovered 1668' of 9 5/8" casing. Spotted 25 sx cement @ 339-375' (bottom of 13 3/8" casing @ 363'). Spotted 10 sx cement in top of 13 3/8" casing. Well P&A 4-14-70.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. H. Can TITLE District Engineer DATE 9-10-70

APPROVED BY John W. Runyan TITLE Geologist DATE JUL 26 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 14 1970

OIL CONSERVATION COM.