

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
REGISTRATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION OFFICE FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS NOV 32 7 57 AM '63

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Hisson Drilling Company				Address % OIL REPORTS & GAS SERVICES BOX 763 HOBBS NEW MEXICO			
Lease Midwest State	Well No. 1	Unit Letter B	Section 14	Township 10 S	Range 33 E		
Date Work Performed 11/15/63	Pool Undesignated			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☒ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Squeezed perfs 9706-09 with 37 sacks cement, maximum pressure 4,500#. Drilled out to 9730. Re-perforated 9705-08 with 2 jet shots per foot and acidized with 500 gallons mud acid. Swabbed 550 bbls fluid cut 90% water. Preparing to install Kobe pump.

Witnessed by R. J. Hisson	Position Vice-President	Company Hisson Drilling Company
-------------------------------------	-----------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 4219.5	T D 9886	P BTD 9865	Producing Interval 9706-09	Completion Date 10/6/63
Tubing Diameter 2 3/8	Tubing Depth 9720	Oil String Diameter 4 1/2	Oil String Depth 9865	

Perforated Interval(s)
9706-09

Open Hole Interval
Penn

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	10/16/63	Swabbed 100% water				
After Workover	11/18/63	55		495		

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

Name

Title

Position

Date

Company

Hisson Drilling Company