

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Sun Oil Company		8. Farm or Lease Name N. Mex. "C" State
3. Address of Operator P. O. Box 1861, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>7</u> TOWNSHIP <u>11S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Inbe Permo Penn.
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) 7-5-72 Halliburton sptd. 3 sx. sd. 9762-9724 & 50 sx. cmt. plug 9729-9179.
- (2) 7-10-72 Bonanza MIRU
- (3) 7-12-72 Sht. 4 1/2" csg @ 5608, stuck. Sht. @ 5028 & pull. Circ. 9.5# mud. Sptd. 50 sx. cmt. plug 5078-4978 & 75 sx. cmt. plug 4050-3788.
- (4) 7-13-72 Sht. 8-5/8" csg 1007. Could not pull.
- (5) 7-14-72 Sht. 8-5/8" @ 900' & 592'. Csg. stuck.
- (6) 7-15-72 Cut off csg. head & sptd. cmt. plug 457-370 & 10 sx. cmt. to surf. Set P&A marker - COMPLETE -

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles L. Lutz TITLE Proration Clerk DATE 8-3-72

APPROVED BY Wattson E. Clegg TITLE OIL & GAS DATE 8-3-72
CONDITIONS OF APPROVAL, IF ANY: