

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 15 1 33 PM '69

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Salt water disposal	7. Unit Agreement Name
2. Name of Operator American Trading and Production Corporation	8. Farm or Lease Name Shell FMF State
3. Address of Operator Post Office Drawer 992, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East 19 TOWNSHIP, 9-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Flying "M" San Andres
15. Elevation (Show whether DF, RT, GR, etc.) unknown	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging operations were performed by Clarke Well Service, Hobbs, New Mexico, August 27, 1969. An attempt was made to pull the Lynes packer, but failed. Tubing was then shot off by the Dia-Log Company at 1295' and 25 sacks cement plug spotted in and out of the tubing and open hole 1285-1315', through the tubing. A second 25 sack cement plug was spotted through the tubing from 450'-380'. Set 10 sack plug in surface and installed 4" marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. Kelly TITLE Production Superintendent DATE September 9, 1969

APPROVED BY John W. Rungas TITLE Assistant Superintendent DATE 10/1/69
CONDITION OF APPROVAL, IF ANY: