

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

AUG 3 11 48 AM '65

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Drilling	5. LEASE DESIGNATION AND SERIAL NO. NM 0450247
2. NAME OF OPERATOR Am American Petroleum Corp.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 68 Hobbs, N.M. 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FSL X 2310' FEL, Sec. 13 (unit J, NW4 SE4)	8. FARM OR LEASE NAME FEDERAL "A"
	9. WELL NO. 6
	10. FIELD AND POOL, OR WILDCAT ROUGH DEVONIAN
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 13-9-35 NM PM
14. PERMIT NO.	12. COUNTY OR PARISH 13. STATE LEA NM
15. ELEVATIONS (Show whether DF, RT, OR, etc.)	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Marcum Drilling Co. spudded 17 1/2" hole 6:00 PM on 7-18-65. On 7-19-65, 13 3/8" OD 35.6-40" SJ + H-40 Casing was set at 455' w/ 400 sq. Incon Neat. Cement Circulated. After N. O. C. 18 hours, tested casing w/ 600 psi for 30 minutes. Test O.K.

Reduced hole to 12 1/4" at 455' and resumed drilling operations.

RECEIVED
JUL 26 1965
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Signed by:

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

JUL 27 1965
J. L. GORDON
ACTING DISTRICT ENGINEER

(0-7)

0-4-USGS
1-WB
1-S&D
1-W/S