

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-21338

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

VA-0333

7. Lease Name or Unit Agreement Name

Shell State

8. Well No.

1

9. Pool name or Wildcat

Wildcat Cuerno Largo Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Manzano Oil Corporation 505/623-1996

3. Address of Operator

P.O. Box 2107/Roswell, NM 88202-2107

4. Well Location

Unit Letter B : 330 Feet From The North Line and 2310 Feet From The East Line

Section 26 Township 10 South Range 32 East NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4297' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/13/95 Wash & ream 5285'.

10/14/95 Swivel parted. Dropped bit & tbg down hole. TIH w/7-5/8" grapel. Caught fish. POOH. LD 20 jts cork screwed tbg plus 18' piece of parted tbg. Left in hole - bit, cross over, eight 4-3/8" drill collars, 12 jts tbg & 12' piece of parted tbg. Tag fish @ 5162'. Bit @ 5792'.

10/15/95 Work over fish @ 5168'. POOH. Did not have any fish.

10/17/95 Looking for fish.

10/18/95 Believe to be beside fish. Did not find fish.

10/19/95 TIH w/junk finder to 5170'. Determined top of fish @ 5147'.

10/24/95 TIH w/7-5/8" Cut-Rite shoe to 5200'. Start cutting iron. Cut from 5202-04' in 4 hrs. Torque but could not make any hole.

10/25/95 Appears to be going down side of tbg again.

(over)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Hernandez

TITLE Engineering Technician

DATE 12/7/95

TYPE OR PRINT NAME Allison Hernandez

TELEPHONE NO. 623-1996

(This space for SIGNATURE OF DISTRICT SUPERVISOR)

DEC 12 1995

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

10/26/95 Finish LD tbg. Rig down pulling unit. Moved off.
11/14/95 MICU.
11/15/95 MICU. Rig up. Wash & ream to 5177'. Start torquing. Work down to 5200'.
Could not get any deeper.
11/16/95 POOH w/tbg & bit. Rig down.
12/04/95 MICU.
12/05/95 TIH w/7-7/8" bit - 4 - 4-3/4" drill collars to base of 8-5/8" csg @ 1415'.
12/06/95 Wash and ream to 8-5/8" stub @ 2250'. Circul clean. Pull back up to 8-5/8"
csg.
12/07/95 TIH to 8-5/8" csg stub @ 2250'. Worked into 8-5/8" csg. Wash down to csg
shoe @ 4500'. Circul clean. Pull back into 8-5/8" csg @ 1415'.

