

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
-	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Southland Royalty Company		Farrar
3. Address of Operator		9. Well No.
1405 Wilco Bldg., Midland, TX 79701		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM		Inbe (Permo-Penn)
THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>11-S</u> RANGE <u>33-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4210.3' GR		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-9-73 - Set CIBP on wire line in 5½" csg @ 9626'. Spotted 5 sacks cement on top of BP @ 9591-9626'.
- 10-11-73 - Shot & recovered 4523' of 5½" csg. Spotted 45 sacks cement 4373-4523'. Spotted 45 sacks cement 3875-4025'.
- 10-13-73 - Shot and recovered 1030' of 8 5/8" csg. Spotted 70 sacks cement 997-1023'. Spotted 70 sacks cement 313-437'. Spotted 10 sacks cement 0-20'.

All plugs placed w/9.5# mud laden fluid between plugs.
Dry hole marker installed.

All work done by Bonanza Casing Pullers, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C.H. Carr</u>	TITLE <u>District Engineer</u>	DATE <u>11-7-73</u>
APPROVED BY <u>John W. Remyer</u>	TITLE <u>Geologist</u>	DATE <u>FEB 11 1974</u>
CONDITIONS OF APPROVAL, IF ANY:		