

Wilson Energy, Inc.  
Activity Report  
New Mexico State "I" No. 1  
660' FNL & 1970.0 FEL (B)  
Sec. 7, T-11-S, R-34 E  
Lea County, New Mexico  
Inbe Bough "C" Formation

2/28/88 - TIH w/Tbg string and latch on to fish - Jar loose  
and POOH - Rec. 60' of tubing. TIH w/3 7/8" X 11"  
Mill Shoe and Shut Down.

3/17/88 - FIH w/ Mill Shoe - Tag Fill @ 8615', wash to 8620'  
Mill and Wash to 8624' and Plugged Tubing - POOH  
and recovered 2 short pieces of Tbg and Collar from  
top of wash pipe.

4/7/88 - TIH w/3 7/8" X 11' 2" Mill Rotary Shoe, Tag Fill @  
8614' - Iron @ 8615' - Mill 2' solid Iron - Cut  
loose and wash 17' - Mill and Wash 10' Iron and Fill  
Circ. hole clean (bottom of work string now @ 8645')  
Pull up hole and Shut Down.

RECEIVED  
APR 11 1988  
OCD  
HOBBS OFFICE