NO. OF COPIES RECEIVED DISTRIBUTION SANTA FE FILE	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 E::ective 1-1-65
U.S.G.S.		5a. Indiante Type of Lease
	site and the second	State 📕 🛛 🗧 🗌
OPERATOR		5, State On & Gas Lease No.
USE "APPLICATI	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVCIP. ION FOR PERMIT	7. Unit Agre ment Name
OIL GAS WELL WELL	0 ั พ E R -	
2. Name of Operator Sun 011		8. Turn of Leose Mano New Mexico "I" State
3. Address of Operator		9. V. St. No.
P. O. Bo	x 2792, Odessa, Texas 79760	1
4. Location of Well		10. Field and Fool, or Wildow
UNIT LETTER	660 FEET FROM THE North LINE AND 1978.9 FEE	Inbe Penn
	DN 7 TOWNSHIP 11 S RANGE 34 B	
	15. Elevation (Show wheth of F, RT, GR, etc.) 4198 Gr.	Lea
^{16.} Check	Appropriate Box To Indicate Nature of Notice, Report	or Other Data
		UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OFNS.	ALTERING CANING
OTHER Well work to ch		to change pumps, encountered ding for re-evaluation.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting day composed work) SEE RULE 1103.
 2. 2. (0. starting on X cont Holl Count of attempted to cull rode Recked off at 51001. Attempted

12-3-69 rigged up X-pert Well Service, attempted to pull rods. Backed off at 5100'. Attempted to pull 2 7/8" tubing, unable to pull @ 90,000#. Ran 159 jts. 1 13/16" lefthanded drill pipe with Bowen evershot. Pulled and recovered additional 131 rods. Reran drill pipe and overshot recovered 3 additional rods. Top of fish appx. 8350'. Reran overshot and drill pipe four additional trips. Recovered 6 additional rods. House ran free point - found 2 7/8" tubing free to top of fish @ 8621'. Pumped 308 bbls fresh water down 2 7/8" tubing @ 800-1000#. Had returns out of 4 1/2" casing and 8 5/8" casing - backed off 2 7/8" tubing at 8613". Pulled 97 jts. Ran 3 7/8" OD rock bit on 2 7/8" tubing. Found top of fish at 8603. Pulled tubing and bit. Ran bridge plug and packer to set packer at 5095'. Tested 4 1/2" casing 1500#, set bridge plug at 8570 w/pkr at 8507. Tested both sides at 1500#. Casing o.k. to 8570. Pulled tubing, bridge plug and packer - ran 2 7/8" tubing w/3 drill collars, accelerator sub and jars - screwed into tubing fish at 8603, jarred 2 hours - fish parted, pulled and recovered 2 7/8" coupling w/pin and ran 2 7/8" tubing w/spear, drill collars, accelerator sub & jars. Caught fish at 8603. Jarred 17 1/4 hours - no movement of fish - pulled out of hole - reran 2 jts. 3 3/4" wash pipe w/ 3 7/8" x 3" clsterite shoe on 2 7/8" tuking. Rigged up reverse unit lowered mill to 8628. Milled 4' over fish - 100% circulation w/mud and steel cuttings. Pulled out of hole - installed well head, left well standing - shut in for further evaluation.

SIGNED / Jag in through the	TITLE Ass't Dist. Superintendent	DATE 1-2-70
APPROVED BY	TITLE	CATE