

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
Dec 2 11 32 AM '66

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 2443
7. Unit Agreement Name
8. Farm or Lease Name LANE STATE
9. Well No. 1
10. Field and Pool, or Wildcat
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Monsanto Company
3. Address of Operator 101 North Marienfeld, Midland, Texas
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 10S RANGE 34E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
furnish later

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

At T.D. of 4030' after running and cementing 8-5/8" casing at 4029' on 11-15-66, the 8-5/8" casing was found to be parted at 2568.5'. After repeated attempts to clean up hole and roll out casing, all of which were unsuccessful, it was decided on 11-28-66 to request approval to plug and abandon the hole. During the attempt to clean up the hole, 1764' of 8-5/8" casing was pulled and 10-3/4" wash over pipe stuck at 1808'.

Hole was plugged and abandoned on 11-28-66 as follows:
 25 sx cement plug at 1770-1726', base stuck 10-3/4" wash over pipe.
 25 sx cement plug at 350-306', base 11-3/4" surface casing.
 10 sx cement plug at surface in 11-3/4" casing.
 Hole was filled with 10# mud between plugs.
 Steel plate welded on top 10-3/4" casing.
 Set 4' x 4" steel marker with location thereon.

You will be notified when location has been cleaned up and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. W. Wood A. W. Wood TITLE Dist. Prod. Supt. DATE 12-1-66
 APPROVED BY John W. Runyan TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY: _____