N. M. OIL CONS. COMMISSION

P. O. BOX 1980

Form 9-331 Dec. 1973	HOBBS, NEW MEXIC		0 8	8240	Form Approved Budget Bureau No. 42-R1424				
Dec. 1373	UNITED STATES		5.	LEASE		3	្វី ភ ភ		
	DEPARTMENT OF THE IN	TERIOR			#18846	=	<u> ज़ुंद्र हुँ</u>	_	
	GEOLOGICAL SURVE	Y RECEIVE	6.	IF INDIAN	, ALLOTTEE (ORTRI	BE NAME		
CUNDO	V NOTICES AND DEDOE		T	UNIT AGR	EEMENT NA	ME.			
	Y NOTICES AND REPOR		مت	<u> </u>		5	ideo ve de		
reservoir. Use F	s form for proposals to drill or to deeper orm 9-331-C for such proposals.)	APR ZJ O 38 A	in ap	FARM OR	LEASE NAMI	: <u> </u>	701 o		
1. oil 🔀	gas well other	BUREAU () 1 4 3 B	1491	WELL NO.	U. ்\$.ஏ்	<u>∓</u> 5	- 14 - 15 - 17 - 15 - 1		
2. NAME O	F OPERATOR	ROSWELL HESON AREA	HUE		#2		71 St.		
	Ran, Inc.		10.	FIELD OR	WILDCAT NA	4	igh Sais Baga		
3. ADDRESS OF OPERATOR				CEC T	Chavero				
P.O. Box 911, Lubbock, TX 79408 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17				AREA	R., M., OR BI	LN.≫AIN ∰	DOURVET	UR	
below.)				ction 3	4, Towns	hip	7S, Rang	ge 32E	
AT SURF	FACE: 1650' FSL & 2310 PROD. INTERVAL:	FWL				13. S			
	L DEPTH:			Rooseve API NO.	<u> 1t- : 원기 </u>		ew Mexic	20_	
16. CHECK	PPROPRIATE BOX TO INDICATE	NATURE OF NOTICE,	1	, , , , ,	NA	2 ₹	6/50 do		
REPORT,	OR OTHER DATA			ELEVATIO	NS (SHOW	`		VD)	
REQUEST FO	OR APPROVAL TO: SUBSEC	QUENT REPORT OF:	L		4493 GR		्रुं <u>च</u> ुल इ		
TEST WATER	SHUT-OFF 🔲	· _				Œ.	2 (
FRACTURE T	_					25	불발함		
REPAIR WELL				(NOTE: Report results of multiple completion or zone					
PULL OR AL MULTIPLE C	TER CASING			chang	e on Form 9–3	30.).	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	•	
CHANGE ZO								- 	
ABANDON*	X					: :		<u>.</u>	
(other)						£:		ž	
17. DESCRI	BE PROPOSED OR COMPLETED C	PERATIONS (Clearly state	te all	pertinent o	details, and	give p	ertinent da	tes, and	
measure	ed and true vertical depths for all m	narkers and zones pertine	nt to	this work.)*	ار المراجع الم المراجع المراجع				
Tr.	emporarily abandon due	to economical re	2 S O T	ns 4/15	5/88	2			
1	emporarity abandon due	to economical ic	ubor			- 1 1 2			
						ë.			
						-			
							15 A A A B A B A B A B A B A B A B A B A		
						•	i E		
						Ė			
						11 A. H. F.	3 \$ 15		
					\$ 4 £ 1 1	i J	or Palls		
Subsurface :	Safety Valve: Manu. and Type				Set	@	<u> </u>	_ Ft.	

18. I hereby certify that the foregoing is true and correct

APPROVED FOR - MONTH PERIOD

ENDING MAY 9 1989
*See Instructions on Reverse Side

MAY 1988

BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA