



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
1962 MAY 8 PM 2:23

Land Office _____
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		
Subsequent report of well conversion to water injection service		X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 4, 1962

Tract 3
Well No. 7-8 is located 1874 ft. from [N] line and 2066 ft. from [E] line of sec. 8
S4E, NE4, Sec. 8 15-S 31-E 18N4E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Caprock (Field) Chaves (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4449 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pulled rods, pump and tubing.
Cleaned out to ETD: 3144'.
Ran 3114' of 2", EUE, 8rt, J-55 tubing to 3124' with Brown tension packer at 3095'. Set packer with 10,000# tension.
Placed well on water injection on April 13, 1962.
Initial injection rate = 483 bbls/day at 1060 Psig.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Oil Company of California

Address 205 E. Washington
Lovington, New Mexico

ORIGINAL SIGNED BY
RICHARD H. BUTLER
UNIT ENGINEER

By Richard H. Butler
Title Unit Engineer