

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>B-10419-22</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	<b>Pebble Queen, Sec. 2</b>
<b>GREAT WESTERN DRILLING COMPANY</b>	8. Farm or Lease Name
3. Address of Operator	9. Well No.
<b>P. O. Box 1659, Midland, Texas 79701</b>	<b>1</b>
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>N</b> LINE AND <b>660</b> FEET FROM	<b>Caprock Queen</b>
THE <b>E</b> LINE, SECTION <b>2</b> TOWNSHIP <b>13-S</b> RANGE <b>31-E</b> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
<b>4390.4 GR</b>	<b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole was loaded with mud and a 35 sack cement plug set @ 3044'. (6-18-68) 1400' of 5 1/2" casing was pulled. A 25 sack plug was spotted @ 1400' and another 25 sack plug set @ 270' with 10 sacks at the surface. A marker was placed. (6-19-68)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. H. Crews TITLE Administrative Coordinator DATE August 30, 1968

APPROVED BY John W. Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: