

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPL. E*
(Other instructions on re-
verse side)

Form approved by
Budget Director, Dept. of the Interior

NMOSC - ARIZONA

GEOLOGICAL SURVEY

5. LEASE DESIGNATION (If different from
6. IF INDIAN, ALLOTTEE OR TRUST NAME

M-025519

NMOSC - MEXICO
BLM - SANTA FE

NOTICES AND REPORTS ON WELLS

Use this form for proposals to drill or to deepen or plug back to a different reservoir.
APPLICATION FOR PERMIT for such proposals.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

WHITE Federal

9. WELL NO.

10. FIELD AND POOL, OR WELLS

FIELD

11. SEC. T. R. S. OR PART OF SURVEY OR AREA

13-9-30 NMP:1

12. COUNTY OR PARISH

CHAVES N.M.

1. OIL WELL GAS WELL OTHER DRILLING

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL * 660' FWL Sec. 13 (Unit M, SW 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GN, etc.)

4137' RDB

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drily Co spreaded 17 1/2" hole 6:30 PM 10-17-67.
On 10-18-67, 13 3/8" OD 48-54.5" J-55 Casing was set
at 495' w/ 500 qt Incon w/ 2% CACK. Cement
circulated. After W. O. C. 12 hours, Tested
casing w/ 1200 psi for 30 minutes. Test O.K.
Reduced hole to 12 1/4" at 495' and resumed drilling.

RECEIVED
OCT 23 1967

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

* Est Vol 450 CF
Upper Dmg. Slurry 85°
Form Slurry Est 70°
Est Stk @ Test 750 psi

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE

10-23-67

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

0+4- USGS- Ros
1- H S W
1- SUSP
1- RRY

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

J. W. Suthala
District F