

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <b>Coastal States Gas Producing Company</b>		5. State Oil & Gas Lease No. <b>K-1318</b>
3. Address of Operator <b>P. O. Box 235, Midland, Texas 79701</b>		7. Unit Agreement Name -
4. Location of Well UNIT LETTER <b>L</b> , <b>1980</b> FEET FROM THE <b>south</b> LINE AND <b>660</b> FEET FROM THE <b>west</b> LINE, SECTION <b>5</b> , TOWNSHIP <b>14S</b> , RANGE <b>33E</b> NMPM.		8. Farm or Lease Name <b>State "5"</b>
		9. Well No. <b>1</b>
		10. Field and Pool, or Wildcat <b>Baum (Penn)</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4267.8' GR</b>		12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well No. 1 was plugged and abandoned as follows:

1. Cut and pulled 5590' of 5-1/2" csg.
2. 35 sx plug @ 5590'.
3. 50 sx plug @ 5500'.
4. 50 sx plug @ 4100'.
5. Cut and pulled 1020' of 8-5/8" csg.
6. 25 sx plug @ 1020'.
7. 25 sx plug @ 380'.
8. 10 sxs in top and DHM.

The casing had collapsed in this well and it was therefore not possible to place a cement plug across the perforations. However, a plug was placed at the 5-1/2" csg. stub.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe E. Howard TITLE Division Production Manager DATE January 26, 1970

APPROVED BY John W. Runyan TITLE Geologist DATE February 2, 1970

CONDITIONS OF APPROVAL, IF ANY: