STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

(
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	_ii
LAND OFFICE	

** ** [**!! * *! (! * () *	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. BOX 2088	Form C-103
SANTAFE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE		5a. Indicate Type of Lease
U.S.G.S.		State X Fee
LAND OFFICE		
OPERATOR]	5. State OH & Gas Lease No.
		K-6444
SUNDE THIS FORM FOR PA	RY NOTICES AND REPORTS ON WELLS CHOSALS TO DRIVE ON TO CELLEN OF PLUC BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT - " FROM C-1011 FOR SUCH PROPOSALS."	
		7. Unit Agreement Name
OIL X WELL .	OTHEM-	
Name of Operator		8. Farm or Lease Hame
Yates Petroleum Cor	poration	Hanladdie WR State
Address of Operator		9. Well No.
207 South 4th St.,	Artesia, NM 88210	1
Location of Well		10. Field and Pool, or Wildcat
v	1090 South 1090	Saunders Permo-Penn
UNIT LETTER K	1980 FEET FROM THE SOUTH LINE AND L980 FEET FROM	THE THE THE THE THE THE
1.T	0 1/.0 225	
THE WEST LINE, SECT	10H 9 TOWNSHIP 14S RANGE 33E HMPM	
		*7777777777777777777777777777777777777
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4235' GR	Lea
Chack	Appropriate Box To Indicate Nature of Notice, Report or Ot	har Data
	• • •	
NOTICE OF I	NTENTION TO: SUBSEQUEN	T REPORT OF:
	PLUG AND ABANDON REMEDIAL WORK	
AFORM REMEDIAL WORK		ALTERING CASING
MPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
LL OR ALTER CABING	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER	

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 17-1/2" hole at 9:00 AM 1-5-83. Ran 13 joints of 13-3/8" 48# K-55 ST&C casing set at 440'. 1-Texas Pattern notched guide shoe set at 440'. Insert float at 410'. Cemented w/450 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 5:15 PM 1-5-83. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. Drilled out 10:15 AM 1-6-83. WOC 18 hours. Nippled up and tested to 1000 psi for 30 minutes, okay. Reduced hole to 9-1/4". Drilled plug and resumed drilling.

i hereby certify that the information above is true and compl	ete to the best of my knowledge and belief.	
" Arainta Dordlett	THE Production Supervisor	
ORIGINAL SIGNED BY		
JERRY SEXTON OVER BY DISTRICT 1 SUPR. (4	*ITUE	PATE JAN 12 1983
DITIONS OF AFFRONCE, II AND		

MONES OFFICE

ì