

DEVIATION TESTS

for

VICTORY III PETROLEUM COMPANY
New Mexico State 22 #1
NE $\frac{1}{4}$ of SW $\frac{1}{4}$, Section 22,
T-16-S, R-33-E
Lea County, New Mexico

DEPTH (FEET)	DEVIATION (DEGREES)	DEPTH (FEET)	DEVIATION (DEGREES)
142	3/4	7,233	1
293	1	7,785	1/2
412	1/2	8,277	1/4
830	3/4	8,785	3/4
1,403	3/4	9,250	3/4
1,658	1/2	9,646	1 1/4
2,443	1/4	10,545	3/4
2,934	1/4	10,825	3/4
3,265	1/2	11,250	1/2
3,611	3/4	11,470	3/4
4,125	3/4	11,753	1 1/4
4,500	3/4	12,061	3/4
4,990	3/4	12,226	1
5,458	1/2	12,626	1/2
5,959	3/4	13,107	3/4
6,230	3/4	13,543	1/2
6,730	3/4	13,705	1/2

B. E. Burton
B. E. Burton, Contract Manager
WARTON DRILLING COMPANY

Subscribed and sworn to before me this 26th day of October, 1977.

Marilyn Neatherlin
Marilyn Neatherlin, Notary Public in and
for Ector County, Texas