

N. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG-3335

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
(SEE APPLICATION FOR PERMIT - FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
1. Name of Operator		
Frank M. Agar		
2. Address of Operator		
P. O. Box 10585, Midland, Texas 79702		
3. Location of Well		
UNIT LETTER E	1980	FEET FROM THE North LINE AND 330 FEET FROM
THE West	LINE, SECTION 27	TOWNSHIP 15-S RANGE 32-E

7. Unit Agreement Name
8. Farm or Lease Name
Nosredna
9. Well No.
1
10. Field and Pool, or Wildcat
Wildcat
11. Elevation (Show whether DF, RT, GR, etc.)
4295.3 GR
12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

REMEDIAL WORK	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input checked="" type="checkbox"/>
OTHER	<input type="checkbox"/>

ALTERING CASING	<input type="checkbox"/>
PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
OTHER	<input type="checkbox"/>

17. Describe any New or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud 8-3-80 & drld 17½" hole to 402'. Ran 13 3/8" csg to TD & cmt'd w/500 sx C1-C w/2% CaCl. Cmt circ'd to surface. Job completed 8-4-80. Drld 12¼" hole to 4180'. Ran 8 5/8" csg to TD. Cmt'd w/1350 sx of Halli Lt Wt w/18# salt, 5#/sk gils., 1/4#/sk flocele (slurry wt 12.9#) followed w/300 sx C1-C w/1/4#/sk flocele + 2% CaCl (slurry wt 14.8#). Pmpd top plug w/fresh wtr @ 3 BPM, 1000 psi. Bumped plug w/2000 psi, 8-14-80. Circ'd 287 sx cmt to surface. Drld 7 7/8" hole out from under 8 5/8" csg to 10,100' TD. Ran DST #1 9925-40' of Bough B zone. Ran Wellex OH logs. Ran DST #2 w/Lynes straddle pkrs between 9837-9934'. Set 35 sk cmt plugs w/bottoms @ 10,100', 9940', 9800', 9300', 7700', 6940' & 5720'; 70 sx @ 4350'-4250' thru 8 5/8" csg shoe; 35 sx @ 2000' & 10 sx in surface. JOB COMPLETED 9-16-80.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dr. R. E. Helm

TITLE Operations Manager

DATE 1-21-81

APPROVED BY [Signature]

TITLE OIL & GAS INSPECTOR

DATE SEP 8 1981

CONDITIONS OF APPROVAL, IF ANY: