

HALLIBURTON SERVICES

TICKET NUMBER: 54826401

TEST DATE: 10-29-87

CLOCK NUMBER: 4099

HOUR: 24

GAUGE NUMBER: 335

GAUGE DEPTH: 10983.0

REFERENCE	TIME (MINUTES)	PRESSURE (PSI)	DP	(T+DT) ----- (T+DT)	(T+DT) LOG----- DT
27	60.0	3780.7	601.2	41.4	0.509
28	70.0	3799.4	619.8	46.0	0.464
29	80.0	3816.8	637.2	50.1	0.427
30	90.0	3832.4	652.7	53.8	0.396
31	100.0	3845.9	666.2	57.3	0.369
32	110.0	3859.1	679.4	60.4	0.346
33	120.0	3871.1	691.4	63.3	0.326
34	135.0	3886.3	706.6	67.2	0.299
35	150.0	3900.0	720.3	70.8	0.277
36	165.0	3915.0	735.3	73.9	0.258
37	180.0	3926.2	746.6	76.8	0.242
38	195.0	3936.0	756.4	79.4	0.227
39	210.0	3944.9	765.2	81.8	0.214
40	240.0	3960.9	781.3	86.0	0.193
41	270.0	3975.2	795.6	89.5	0.175
42	300.0	3987.1	807.4	92.6	0.160
43	360.0	4004.5	824.9	97.6	0.137
44	420.0	4019.1	839.5	101.5	0.120
45	480.0	4029.8	850.2	104.7	0.107
46	540.0	4038.7	859.0	107.3	0.096
47	600.0	4046.0	866.3	109.5	0.088
G 48	626.4	4050.1	870.4	110.3	0.084

NOTICE, THIS REPORT IS BASED ON SOUND ENGINEERING PRACTICES, BUT BECAUSE OF VARIABLE WELL CONDITIONS AND OTHER INFORMATION WHICH MUST BE RELIED UPON HALLIBURTON MAKES NO WARRANTY, EXPRESS OR IMPLIED, AS TO THE ACCURACY OF THE DATA OR OF ANY CALCULATIONS OR OPINIONS EXPRESSED HEREIN. YOU AGREE THAT HALLIBURTON SHALL NOT BE LIABLE FOR ANY LOSS OR DAMAGE, WHETHER DUE TO NEGLIGENCE OR OTHERWISE, ARISING OUT OF OR IN CONNECTION WITH SUCH DATA, CALCULATIONS OR OPINIONS.

