



The Ohio Oil Company
 Lea Devonian - Lea Bone Springs
 Oil - Oil Dual
 Lea County, New Mexico
 Initial Packdr Leakage Test
 4-12-61

Pressure - PSI
 Time - Hours

Flow Test No. 1
 Flow Test No. 2

Pre-Test Shut-In
 Mid-Test Shut-In
 Flow Test No. 2

DWT 1672
 DWT 1472
 DWT 1674
 DWT 1499
 DWT 1503
 DWT 220
 DWT @ 3:PM 231
 DWT @ 5:PM 231

4-2-61
 4-3-61
 4-4-61
 4-5-61

KUFFEL & ESSER CO.
 MADE IN U.S.A.