

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

046164

Serial Number

Lease or Permit

Hazel Wolff Andrews Permit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT RECORD OF SHOOTING.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		RECORD OF PERFORATING CASING.....	
NOTICE OF DATE FOR TEST OF WATER SHUT-OFF.....		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING.....	
REPORT ON RESULT OF TEST OF WATER SHUT-OFF.....		NOTICE OF INTENTION TO ABANDON WELL.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO SHOOT.....		SUPPLEMENTARY WELL HISTORY.....	
Notice of intention to Acidize	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Monument, N.M. January 19, 1936, 19

Following is a {notice of intention to do work} on land under {permit} described as follows:
~~report of work done~~ ~~lease~~

New Mexico **Lea** **Monument**
 (State or Territory) (County or Subdivision) (Field)
 Well No. **2** **0 NE 1/4, NE 1/4, 11** **20-6** **36-4**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

The well is located **660** ft. **N** of **N** line and **660** ft. **E** of **E** line of sec. **11**

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF PLAN OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

This well was completed at a total depth of 3895' and 2 1/2" tubing run to a depth of 3882'. Well was swabbed in and produced 6,500,000 cu. ft. gas and no oil. A Robinson canvas packer was then set at 3805' with perforations below and well swabbed in. Produced at the rate of 5 barrels of oil by swabbing. Well was then treated with 2,000 Gal. Dowell acid below packer. Acid went in under vacuum.

Approved _____
 (Date)

Company **Anarada Petroleum Corporation**

By *J. A. Murphy*

Title _____
 GEOLOGICAL SURVEY

Title **Pack Boss**

Address _____

Address **Monument, New Mexico**

NOTE.—Reports on this form to be submitted in triplicate to the Supervisor for approval.

