Form 9-881 a (Masch 1942)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No. 031695 (6)

SECEIVED.

R 7 1951

SUNDRY NOTICES AND REPORTS ON

	LIOSES - LIO
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEMU-Marren A-30 No. 2	- habbs, liew her	*1co
Well No is locat	ed 1980 ft. from \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	60 ft. from line of sec30
Marko, and Star Rey 30	(Failge)	(Marithan)
(Flaid)	(County or Subdivision)	(State or Territory)

The elevation of the derrick floor above sea level is __2520. ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

Set 7" casing at 3705' and commuted with 1210 sacks commut. Total depth of hole 3707' in lime. Plug down 5:40 A.E. 2-20-51. Top of coment behind casing 675' by temperature survey.

On 2-25-51, pressure tested casing with 1200# for 30 minutes. Final pressure 1185#. Found top of coment plug at 3637°. Drilled out coment plug and tested easing with 1200# for 30 minutes. Final pressure 1170#.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company Continental Oil Company		
Address GC		
	By Dansa	
	Title Aget District Smarint ander	