

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. LC-062032

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

1951 JUN 9 AM 7:43

U. S. GEOLOGICAL SURVEY  
ALBUQUERQUE, NEW MEXICO

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<b>XX</b>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Federal-Gilmore**

**June 1, 1954**

Well No. 1 is located 1980 ft. from S line and 660 ft. from E line of sec. 21  
SE 1/4 of Sec. 21 T-22-S R-32-E N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wilcox Lee New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft. **Unknown at present**

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Reamed 7-7/8" hole to 10-5/8" to 4814 feet.  
 Cemented 8-5/8" casing at 4807.47' with 150 sz. 4% gel cement.  
 Waited on cement 48 hours. Top of cement at 4050 feet.  
 Tested casing with 1000# for 30 min. O.K.  
 Prep. to drill ahead.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Oil Company of California

Address 200 Wilkinson-Foster Building

Midland, Texas

By James E. Ryan

Title Asst Division Engineer

1

—

100

— 274 —