

CARPER

DRILLING COMPANY, INC.

O I L P R O D U C T I O N A N D D R I L L I N G

EMERY CARPER, PRESIDENT
STANLEY CARPER, VICE PRES.
MARSHALL ROWLEY, VICE PRES.

ARTESIA, NEW MEXICO
CARPER BUILDING
TELEPHONE 147 L. O. 847

May 23, 1955

E. S. Walker
Commissioner of Public Lands
Box 791
Santa Fe, New Mexico

In Re: New Mexico State Lease E-268-2
W/2, W/2 NE/4 Sec. 12
N/2 NW/4 Sec. 22, all in Township 22S,
Range 35 E., Lea County, New Mexico

Dear Sir:

Below is a progress report on the Carper-Randel State 1-C located in the NE/4 NW/4 of Section 12, Township 22 South, Range 35 East covering the period from April 29, 1955 to May 23, 1955.

4-29-55 W.O.C. and drilling out cement to 3892'.
4-30-55 Ran logs, perforated from 3866 - 3890' and sandfraced with 10,000 gals oil & 20,000# sand.
5-1-55 Swabbing back oil from treatment.
5-2-55 Swabbed hole dry, treatment not successful, ran bridging plug and set @ 3852, perforated casing from 3780'-3820'.
5-3-55 Sandfraced w/10,000 gallons oil & 20,000# sand.
5-4-55 Well shut in to allow pressure to equalize.
5-5-55 Pressure did not lower, well swabbed down, started flowing
5-6-55 Well shut in for pressure build up.
5-7-55 " " "
5-8-55 " " "
5-9-55 " " "
5-10-55 Pressure did not build, so started swabbing.
5-11-55 Swabbed well down, don't have all of the treating oil back.
5-12-55 Lowered tubing to test bridging plug.
5-13-55 Bridging plug holding all right. Some treating sand in bottom. Swabbing
5-14-55 Swabbed well and tested.
5-15-55 Well shut in for pressure buildup.
5-16-55 No pressure buildup.
5-17-55 Pulled tubing to clean out sand
5-18-55 Cleaning out sand.
5-19-55 " " "
5-20-55 Drilling on bridging plug.
5-21-55 " " "
5-22-55 Bridging plug driven to bottom of hole, drilling on it and float shoe. Will drill well deeper when hole is cleaned up.

CARPER DRILLING COMPANY, INC.

Marshall Rowley
Marshall Rowley

MR:CC

CC: Oil Conservation Office, Hobbs