


NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS



Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

P.O. Box #1231 - Midland, Texas

October 24, 1944

Place

Date

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
Tide Water Associated Oil Company State **"N"** Well No. **1** in the _____
 Company or Operator

SW/4 of the SW/4 of Sec. **19**, T. **22-S**, R. **35-E**, N. M. P. M.,
Wildcat Field, **Lea** County.

The dates of this work were as follows: **October 15, 16 and 17, 1944.**

Notice of intention to do the work was ~~(was)~~ submitted on Form C-102 on **October 14** 19 **44**
 and approval of the proposed plan was ~~(was not)~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

The hole was filled with heavy mud to 4125', bridged, and a cement plug of 20' dumped with a dump bailer on top of the bridge (top of plug - 4105'). Then the hole was filled with heavy mud to 1850', bridged, and a cement plug of 32' dumped with a dump bailer on top of the bridge (top of plug - 1818'). All casing was recovered except the 10" which was shot at 645', leaving 223' in the hole. The remaining hole was filled with mud and a 6' cement plug put in top of the 16" surface casing and a regulation marker erected.

Witnessed by **E.L. Layman** - **Tide Water Associated Oil Company** - **Foreman**
 Name Company Title

State of Texas

County of Midland

Subscribed and sworn before me this _____

24th day of October, 1944

Dorothy Dickey
 Dorothy Dickey Notary Public

My commission expires June 1, 1945

I hereby swear or affirm that the information given above is true and correct.

Name **Elmer Lamb**

Position **District Foreman**

Representing **Tide Water Associated Oil Company**
 Company or Operator

Address **Drawer #1231 - Midland, Texas**

Remarks:

Roy. Garbrough
 Name
 GAS INSPECTOR
 Title

Orig. & cc - Con. Comm. - Hobbs, N.M. ✓
 cc - Tulsa, Houston, Midland (to CC for approval), Hobbs.

