State of New Mexico

Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. P.O. Box 2088 30-025-06758 DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE | DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) TURNER Type of Well: GAS X WELL OTHER WATER SOURCE 2. Name of Operator 8. Well No. Shell Western E&P inc. 3. Address of Operator (WCK 4465) 9. Pool name or Wildcat P.O. Box 576 Houston, TX 77001-0576 HARE-SAN ANDRES 4. Well Location Unit Letter M: 330 Feet From The SOUTH 660 Feet From The Line and WEST Section ship 21S Range 37E

10. Elevation (Show whether DF, RKB, RT, GR, etc.) Township NMPM I FA County 3427' DF Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER: ACD/REP SUBMERS EQMT 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-27 TO 3-09-93: POH W/TBG & SUBMERS PMP. SET RBP @ 3100'. RIH W/SUBMERS PMP ON 1 JT TBG. PMP 420 GAL 15% HCL DWN BACKSIDE ONTO PMP. PMP 1050 GAL 15% HCL DWN PMP. POH W/PMP. CIRC ACID OUT INTO FRAC TANK. RIH & FOUND RBP HAD SLIPPED TO 4614'. LATCHED ONTO RBP & RESET @ 3800'. PT CSG TO 500#, HELD. LATCHED ONTO RBP & POH. TAG FILL @ 4875' W/BIT & SCRPR, POH. PMP 40,824 GAL CHEM MIX. RIH W/SUBMERS PMP ON 84 JTS 4-1/2 IN. TBG. CLN LOC. RTP. 3-21 TO 3-24-93: POH W/TBG & SUBMERS PMP. FOUND CRACKED CLR ON DISCH PMP HD. CHNG OUT CLR. RIH W/SUBMERS PMP ON 84 JTS 4-1/2 IN. TBG. FOUND COATING WAS COMING LOOSE ON 1 JT OF 4-1/2 IN. TBG. LAID DWN BAD JT. SET BTM OF MOTOR @ 2610'. CLN EQMT & LOC. RTP. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TECH. MANAGER - ASSET ADMIN. DATE 4/19/93 544 TYPE OR PRINT NAME (J. L. MORRIS TELEPHONE NO. 713/270-3797 (This space for State BiRIGINAL SASINGS BY JARRY SEXTON DISTRICT I SUPPRVISOR

APR 27 1993

CONDITIONS OF APPROVAL, IP ANY:

APPROVED BY ...