

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Ollie J. Boyd
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201		9. Well No. 5
4. Location of Well UNIT LETTER E , 2160 FEET FROM THE North LINE AND 330 FEET FROM THE West LINE, SECTION 23 TOWNSHIP 22-S RANGE 37-E N.M.P.M.		10. Field and Pool, or Wildcat Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3336' GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned in the following manner:
Loaded hole w/9# gel mud w/25 sx gel/100 BW. Spotted 30 sx Class H cement from 4811-5086'. Shot off 5½" casing @ 3145'. Pulled 99 jts (3135.49') of 5½" OD 8R J-55 17# ST&C casing. Spotted 30 sk cement plug from 3062-3185'. Spotted 30 sk cement plug 2740-2850' (7-5/8" shoe @ 2801'); Placed 10 sk cement plug in top of well and erected dry hole marker. 7-5/8" and 10-3/4" casing strings remain intact. Well P & A 3/27/72.

Your office will be notified when this location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>D.D. Litcher</u>	TITLE <u>Dist. Drlg. Supervisor</u>	DATE <u>3/29/72</u>
APPROVED BY <u>Leslie N. Clement</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JUL 1 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		