

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Campbell & Hedrick, P.O. Box 463, Midland, Texas
(Address)

LEASE Allie M. Lee WELL NO. 1 UNIT I S 26 T 22-S R 37-E

DATE WORK PERFORMED Feb. 21-24, 1959 POOL Drinkard

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Perforate & Sand fracture

Detailed account of work done, nature and quantity of materials used and results obtained.
Perforated $5\frac{1}{2}$ " csg. w/Lane Wells 2/21/59 6320-30, 6336-46, 6350-54, 6366-76, 6416-19, and 6425-28 w/2 $\frac{1}{2}$ " holes per foot. Sand fractured above perforations with 12,000 gal. refined oil and 12,000 # sand with Dowell, Inc. Rate average 15 BPM. Maximum pressure 4600 #. Work complete February 24, 1959.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____	_____	_____
	(Company)	

OIL CONSERVATION COMMISSION

Name [Signature]
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Joe H. Campbell
Position Partner & Pat. Engr.
Company Campbell & Hedrick

Work complete February 24, 1929.
 oil and 12,000 1/2 sand with Duvell, Inc. Rate average 12 BPM. Maximum pressure 4000 1/2.
 6422-28 w/2 1/2 holes per foot. Sand fractured above perforations with 12,000 gal. refined
 Perforated 2 1/2" esp. w/ Lane Wells 2/21/29 6320-30, 6326-46, 6320-24, 6366-76, 6416-19, and

x Perforate & sand fracture

Feb. 21-24, 1929
 I
 I
 26
 22-2
 27-2

Campbell & Hedrick; P.O. Box 463; Midland, Texas

Campbell & Hedrick
 Partner & Prof. Eng.
 Joe M. Campbell