

HOBBS SEP 1953
Form O-103
Revised 3-55
DEC 17 PM 2 43

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY RESLER & SHELTON 302 Carper Building, Artesia, New Mexico
(Address)

LEASE Allie Lee WELL NO. 1 UNIT I S 26 T 22S R 37E
DATE WORK PERFORMED 12-13-57 POOL Drinkard

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled to 7520 feet. Left hole full of mud. Halliburton set 20 sack cement plugs from 6400-6500, 5050-5150, from about 1200-1300 and at base of 13 3/8" casing. Before setting last two plugs ran free point test, shot off 8 5/8" @ 1250' and recovered that much 8 5/8" casing. Set surface marker in a 30" cement plug. This program as approved in phone call with Mr. Fischer on December 12, 1957.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		
		(Company)

OIL CONSERVATION COMMISSION

Name *Anthony*
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name *Vilas P. Shelton*
Position Partner
Company RESLER & SHELTON