

		X

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 1C030556 b

Unit N.M.F.U.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Subsequent Report of Setting Liner & Recompletion			X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Stevens B-18 Unit

September 5, 1958

Well No. 1 is located 990 ft. from N line and 1650 ft. from E line of sec. 18

NE/4 Sec. 18
(1/4 Sec. and Sec. No.)

23 S
(Twp.)

37 E
(Range)

N.M.P.M.
(Meridian)

Jalisco
(Field)

Lee
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3349 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER - TD 3660', Sand, PB 3050', DF 10', Elev 3349. Pay Yates 2689-3050' open hole, Csg Pt 2689'. Prior to workover well produced 1527 MCF gas during the first 17 days of July, 1958.

WORK DONE - Cleaned out to 3089'. Drilled cement plug. Cleaned out to 3332'. Set 4" liner from surface to 3332' w/185 SZ. Ran Depth Control GR Survey. Perfs 2771-77', 2793-96', 2814-32', 2851-60', 2884-88', 2925-33', 2937-41', 2785-89', 2947-54', 2957-86', 2999-3002', 3050-3119', 3153-64', 3171-79', 3259-64', 3288-3304', w/2 jets per ft. Waterfraced w/75,000 Gals.

AFTER WORKOVER - TD 3360', PB 3332'. DF and Elev same. Pay Yates 2771-3304'. Perfs 2771-77', 2785-89', 2793-96', 2814-32', 2851-60', 2884-88', 2925-33', 2937-41', 2947-54', 2957-86', 2999-3002', 3050-3119', 3153-64', 3171-79', 3259-64', 3288-3304'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Bunice, New Mexico

By _____

Title District Superintendent

Cale open flow pot 482 MCFPD. Del at 600 PSIG is 377 MCFPD, and at 150 lbs
PSIG is 462 MCFPD. SIP 1001.2 lbs PSIA. Est allow 170 MCFPD. Tested 8-24-58.
Work started 7-21-58, completed 8-1-58.