

WELL COMPLETION OR RECOMPLETION REPORT AND LOG - LYNN B-1 NO. 11

Page-2

Formation	Top	Bottom	Description	Geologic Markers	
				Name	Neas Depth
Queen	3180	3510	Core #1 - 50.4 Ft. Dolo, Dense shly, SS to NS W/SI Fract 3 ft Dolo Good Porosity, Stain & Flour 1 ft. Dolo W/ Poor Interxline Porosity Bleeding oil & gas .6 ft mod hard SH N.S. 6 ft SS qtz, NS to fair SH, fair to good porosity.	Ruslter	1170
				B/Salt	2805
				Yates	2965
				Seven Rivers	3180
				Queen	3586
	3510	3600	Core #2 - 2 Ft. SS Dolomite NSW/VSSH 13 Ft-SS qtz, NS to GS W/Good porosity stain, Odor Dolo, Dense Sll to fair porosity, none to good vuggy		
	3600	3660	Core #3 - 30 Ft SS-VFG, No SH to fair SH W/some bleeding, scat hairline fract 30 ft. Dolo, Dense, NS to sll sh a few scat vugs & small fractures, scat stain & Bleeding.		
	3660	3686	4 ft. SS, stained, sll bleeding in horiz fract, fair SH 2 ft SH, no sh 20 ft dolo, dense, heavy stain, a few scat vugs & small fract, bleeding from scat fract, fair to no show.		
	3686	3725	4 ft. SS, Dolomite qtz, NS, Poor Staining & Bleeding, 2 ft SS, VFG, V Dolo, Fair Vug NS 29 ft - Dolo mostly dense but some sll bleeding fm Random fract & PPP, Fair to NS 4 Ft - streaks of SS, Dolo, SH, NS		