

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Amoco Production Company

3. ADDRESS OF OPERATOR
P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL X 1980' FEL, Sec. 6
AT TOP PROD. INTERVAL: (Unit J, NW/4, SE/4)
AT TOTAL DEPTH:


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF
- FRACTURE TREAT
- SHOOT OR ACIDIZE
- REPAIR WELL
- PULL OR ALTER CASING
- MULTIPLE COMPLETE
- CHANGE ZONES
- ABANDON*
- (other)

SUBSEQUENT REPORT OF:

Status Report



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Continued drilling to 10-9-81. Ran 4-1/2" liner set at 16453'. Top of liner 15185'. Cement with 200 sacks Class H. Pull out of liner and cement top of liner with 150 sacks Class H. WOC 18 hr. Drill out stringers and test casing to 1000 PSI. Tested OK. Rig released 10-26-81. No further report until completion unit is moved in.

0+4-USGS, H 1-Hou 1-Susp 1-W. Stafford, Hou 1-DMF 1-Superior

Subsurface Safety Valve: Make and Type _____ Set @ _____ Ft.

13. I hereby certify that the above is true and correct

SIGNED *Mark L. ...* TITLE Ast. Adm. Analyst DATE 11-12-81

ACCEPTED FOR RECORD
ROBERT A. CHAPMAN
NOV 16 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

APPROVED BY _____ TITLE _____ DATE _____