

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Ave., Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-08190
5. Indicate Type of Lease FEDERAL STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LC - 062300
7. Lease Name or Unit Agreement Name: Cotton Draw Unit
7. Well No. 12
9. Pool name or Wildcat Paduca Delaware
4. Well Location Unit Letter <u>E</u> : 1980 feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>15</u> Township <u>25-S</u> Range <u>32-E</u> NMPM County <u>Lea</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3448' DF

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
 1. Type of Well:
 Oil Well Gas Well Other : TA

2. Name of Operator
 SAHARA OPERATING COMPANY

3. Address of Operator
 P.O. BOX 4130, Midland, TX 79704

4. Well Location

 Unit Letter E : 1980 feet from the North line and 660 feet from the West line

 Section 15 Township 25-S Range 32-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3448' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING MULTIPLE COMPLETION
 OTHER:

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
 CASING TEST AND CEMENT JOB
 OTHER: Request TA status

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

7-31-01 RU Rapid Transport. Tested casing to 540 PSI for 30 minutes, held OK. Job witnessed by OCD.
 Request TA status while Unit is studied for improved recovery operations.

This Approval of Temporary Abandonment Expires 9/10/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE 9-5-01


Type or print name Robert McAlpine Telephone No. 915-697-0967

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any:

100



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

SAHARA Oper.

CDU #12

E-15-25-32

7-3101

BR 221 B.H.S.

WEST CONTOUR

Repeat Team
1000#
2 hr.
last call 3-2-01
Del Star

MIDNIGHT

6 P.M.

5

4

3

2

1

NOON

11

10

9

8

6 A.M.

5

4

3

2

1

MIDNIGHT

11

10

9

8

7

