



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**
Lease No. **NM 0321613**
Unit **C**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent Report to Plugback and Recomplete	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Jack B-26

August 21, 1963

Well No. 1 is located 660 ft. from N line and 1980 ft. from W line of sec. 26

NE/4 NW/4 Sec. 26 24-S 37-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
NMPU Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3209 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER: TD 3604 Lm, DF 10, Elev 3199 AGL. Pay Queen Sand 3300-3450. Csg Pt 7" at 3258. Open hole 3258-3604. Well was TSD.
WORK DONE: Set CIBP at 3200 w/2 sx cat on top. PBD 3186. Perf Yates and 7-Rivers 2682-85, 2704-06, 2856-60, 2871-73, 2950-54, 2992-96, 2 3026-30, & 3048-52. Attempted to water frac perfs 2682-3052. Failed to break down. Spotted 500 gal acid across perfs. Trtd perfs 2682-3052 w/1500 gal 15% Type J acid fol by frac using 10,000 gal wtr & 10,000 lb sand. **AFTER WORKOVER:** TD 3604 Lm, FB 3186 DF, DF 10, Elev 3199 AGL. Pay Yates & 7-Rivers 2682-3052, NEP 0. Csg Pt 7" at 3258. Perfs - Same as above (2682-3052). Well swbd 10 BW in 6 hrs. Had only trace of gas. CP 350, TP 0. Workover unsuccessful. No oil or gas obtained in commercial quantities. Well TSD. Workover started 7-28-63, Comp 8-12-63, Tstd 8-12-63.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company
Address Box 68
Hunice, New Mexico

By _____
Title Dist. Supt.

USGS-4 NMOCC-2 ABS File
Pan Am-Hus-3 Atl-Rosw-2
Calif Oil-Hous, Mid-1 each