




Figure 11. Combined Results of Geophysical Logging, Core Analysis and Reservoir Tests at Eunice Gas Plant SWD #1