



Case No.
4518

Large Exhibits





Water Damaged Documents


Document Number: #4518


Field Number: 27

Field Number: 180

Date: 1-4-88

Drawn by: John B. Lee






LEGEND
 VACA DRAW UNIT
 RED HILLS UNIT
 WOLF CAMP PW




VACA DRAW UNIT
 LEA COUNTY, NEW MEXICO
 PROPOSED 17,500' SILURO-DEVONIAN TEST
 CONTOURED: T/ SILURO-DEVONIAN (ADJUSTED)
 CONTOUR INTERVAL: 100' SCALE: 1" = 2000'
 Geology: W. J. Henry


#3
 Affiliates
 Case 4518



U.S. GEOLOGICAL SURVEY
 WATER RESOURCES DIVISION
 DEPARTMENT OF THE INTERIOR
 WASHINGTON, D.C. 20506
 This document is a preliminary report and should not be used for legal purposes.
 For information only
 Water Damaged Documents
 DOCUMENT NUMBER: 4518
 REEL NUMBER: 27
 FRAME NUMBER: 180-131
 DATE: 1-4-88
 SHIPPED OUT BY: Jydo Bla







LEGEND
 VACA DRAW UNIT
 RED HILLS UNIT
 WOLF CAMP

VACA DRAW UNIT
 LEA COUNTY, NEW MEXICO
 PROPOSED 17,500' SILURO-DEVONIAN TEST
 CONTOURED: T/ SILURO-DEVONIAN (ADJUSTED)
 CONTOUR INTERVAL: 100' SCALE: 1" = 2000'
 Geology: W. J. Henry

BEFORE EXAMINER UTZ
 IL CONSERVATION COMMISSION
 EXHIBIT NO. 3
 CASE NO. 4-518



U.S. GEOLOGICAL SURVEY
 WATER RESOURCES DIVISION
 RESTON, VIRGINIA 20192
 WATER DAMAGED DOCUMENTS
 DOCUMENT NUMBER: 4518
 FIELD NUMBER: 27
 FRAME NUMBER: 180-191-182-183
 DATE: 1-4-88
 SHOWN OUT BY: Jyda Baa

