

Case No.

4563

Large Exhibits





Figure 1. Schematic representation of the experimental design.

Water Damaged Documents


00-15811-10100 # 4563

REF. NUMBER 27


PAGE 12 OF 33 334

DATE 1-5-88








REPORTED BY M. Hernandez



BEFORE EXAMINER UTZ
OIL CONSERVATION COMMISSION
EXHIBIT NO. 4
CASE NO. 4563
Submitted by CLARENCE GRACE
3-1-79



PREPARED ON TOP OF QUEEN SAND
(HORIZONTAL DISTANCES NOT TO SCALE)

[illegible]

BEFORE EXAMINER UTZ
OIL CONSERVATION COMMISSION
EXHIBIT NO. 5
CASE NO. 4563
Submitted by: Corinne Gence
Hearing Date:

Ex 5




✓ *Water Damaged Documents*

DATE: 1-5-88


FILE NUMBER: 334-335

SEARCHED BY: M. Hernandez





NE - S, SW CROSS SECTION B-B
TOP OF QUEEN SAND
DOUBLE "L" FIELD
CHAVES COUNTY, NEW MEXICO

NOTE: Horizontal Distances Not To Scale



BEFORE EXAMINER UTZ
OIL CONSERVATION COMMISSION
CASE NO. 4563
EXHIBIT NO. 6
Submitted by Caroline George





Water Damaged Documents
 Case # 4563
 Date 2/27
 Pages 334-335-336-337
 Date 2-5-88
 Submitted by M. Hernandez

