





Case No.
2272
Large Exhibit










17	16	15	14	13	12	11	10	9	8
20	21	22	23	24	19	20	21	22	23
29	28	27	26	25	30	29	28	27	26
32	33	34	35	36	31	32	33	34	35
5	4	3	2	1	6	5	4	3	2
8	9	10	11	12	7	8	9	10	11
17	16	15	14	13	18	17	16	15	14
24	23	22	21	20	19	20	21	22	23


T
28
N

T
27
N

R-M-W







PAN AMERICAN PETROLEUM CORPORATION
**CHA CHA GALLUP POOL
SAND THICKNESS ISOPACH**

C. 1 = 2'
SCALE: 1" = 2000'

■ NON STANDARD UNIT
● UNORTHOGONAL LOCATION

BEFORE EXAMINER NUTTER
FOR CONSERVATION COMMISSION
FILE NO. 2272