

**1RF-26 - Chili
Pepper Water
Recycling Facility
and Containment
Pit Facility ID
[f0Y1805031625
C-147/Annual
Extension**

**EOG RESOURCES INC
[7377]
01/12/2023**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☒ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain) _____

*** At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.
Operator: EOG Resources Inc. (For multiple operators attach page with information) OGRID #: 7377
Address: 5509 Champions Dr. Midland, Texas 79706
Facility or well name (include API# if associated with a well): Chili Pepper Water Recycling Facility and Containment Pit
OCD Permit Number: 1RE-26 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr NENW (C) Section 17 Township 23S Range 35E County: Lea
Surface Owner: ☐ Federal ☐ State ☒ Private ☐ Tribal Trust or Indian Allotment

2.
☒ **Recycling Facility:**
Location of recycling facility (if applicable): Latitude 32.3099405 Longitude -103.3922060 NAD83
Proposed Use: ☐ Drilling* ☒ Completion* ☐ Production* ☐ Plugging *
***The re-use of produced water may NOT be used until fresh water zones are cased and cemented**
☐ Other, **requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.**
☒ Fluid Storage
☒ Above ground tanks ☐ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.
☒ **Recycling Containment:**
☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude 32.3099372 Longitude -103.3939422 NAD83
☐ For multiple or additional recycling containments, attach design and location information of each containment
☒ Lined ☒ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other _____
☐ String-Reinforced
Liner Seams: ☒ Welded ☐ Factory ☐ Other _____ Volume: 1MM bbl Dimensions: L 600 x W 600 x D 16(inside)
☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC **(These containments are limited to only the wells owned or operated by the owners of the containment.)**
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ **(work on these facilities cannot commence until bonding amounts are approved)**
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify _____

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

- Written confirmation or verification from the municipality; written approval obtained from the municipality

☐ Yes ☒ No
☐ NA

Within the area overlying a subsurface mine.

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

☐ Yes ☒ No

Within an unstable area.

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

☐ Yes ☒ No

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

- Topographic map; visual inspection (certification) of the proposed site

☐ Yes ☒ No

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

☐ Yes ☒ No

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

☐ Yes ☒ No

Within 500 feet of a wetland.

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

☐ Yes ☒ No

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations –
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Patricia Donald Title: Regulatory Specialist

Signature: Patricia Donald Date: 01/11/2023

e-mail address: patricia_donald@cogresources.com Telephone: 432-488-7684

11.

OCD Representative Signature: Victoria Venegas Approval Date: 01/12/2023

Title: Environmental Specialist OCD Permit Number: 1RF-26

☒ OCD Conditions _____

☒ Additional OCD Conditions on Attachment

Permit Name Chili Pepper Reuse Water Facility and Containment Pit
Permit Number 1RF-26-0

Run Date	Start Time	Visual Inspection Conducted?	Visible Layer of Oil on Surface?	At least 3' of Freeboard?	Is the Liner Free of Damage?	Was the Leak Detection System Run?	Is the Leak Detection System Working Properly?	Recycling Containment and Leak Detection Notes
4/27/2018	9:00	Y	N	Y	Y	Y	Y	Liner inspected for first fill
5/4/2018	18:00	Y	N	Y	Y	Y	Y	No new observations
5/7/2018	12:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
5/21/2018	22:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
5/22/2018	6:00	Y	N	Y	Y	Y	Y	No new observations
5/28/2018	9:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
6/2/2018	18:00	Y	N	Y	Y	Y	Y	No new observations
6/8/2018	12:00	Y	N	Y	Y	Y	Y	No new observations
6/14/2018	22:00	Y	N	Y	Y	Y	Y	No new observations
6/21/2018	15:00	Y	N	Y	Y	Y	Y	No new observations
6/26/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
7/3/2018	18:00	Y	N	Y	Y	Y	Y	No new observations
7/9/2018	12:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
7/16/2018	22:00	Y	N	Y	Y	Y	Y	No new observations
7/21/2018	6:00	Y	N	Y	Y	Y	Y	No new observations
7/28/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
8/3/2018	12:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
8/9/2018	22:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
8/16/2018	6:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
8/21/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
8/26/2018	18:00	Y	N	Y	Y	Y	Y	No new observations
9/1/2018	12:00	Y	N	Y	Y	Y	Y	No new observations
9/7/2018	22:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
9/14/2018	15:00	Y	N	Y	Y	Y	Y	No new observations
9/19/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
9/26/2018	18:00	Y	N	Y	Y	Y	Y	No new observations
10/2/2018	12:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
10/7/2018	12:00	Y	N	Y	Y	Y	Y	No new observations
10/13/2018	22:00	Y	N	Y	Y	Y	Y	No new observations
10/20/2018	15:00	Y	N	Y	Y	Y	Y	No new observations
10/25/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
11/1/2018	18:00	Y	N	Y	Y	Y	Y	No new observations
11/7/2018	12:00	Y	N	Y	Y	Y	Y	No new observations
11/14/2018	22:00	Y	N	Y	Y	Y	Y	No new observations
11/19/2018	6:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
11/26/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
12/2/2018	12:00	Y	N	Y	Y	Y	Y	No new observations
12/7/2018	22:00	Y	N	Y	Y	Y	Y	No new observations
12/13/2018	6:00	Y	N	Y	Y	Y	Y	No new observations
12/19/2018	9:00	Y	N	Y	Y	Y	Y	No new observations
12/26/2018	22:00	Y	N	Y	Y	Y	Y	No new observations
12/31/2018	6:00	Y	N	Y	Y	Y	Y	No new observations
1/7/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
1/12/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
1/19/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
1/28/2019	22:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
1/31/2019	15:00	Y	N	Y	Y	Y	Y	No new observations
2/6/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
2/13/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
2/19/2019	12:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
2/25/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
3/3/2019	22:00	Y	N	Y	Y	Y	Y	No new observations
3/8/2019	15:00	Y	N	Y	Y	Y	Y	No new observations
3/14/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
3/20/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
3/27/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
4/1/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
4/8/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
4/14/2019	22:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
4/19/2019	15:00	Y	N	Y	Y	Y	Y	No new observations
4/26/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
5/3/2019	18:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
5/7/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
5/13/2019	22:00	Y	N	Y	Y	Y	Y	No new observations
5/17/2019	6:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
5/26/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
6/2/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
6/7/2019	22:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
6/12/2019	6:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
6/20/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
6/26/2019	22:00	Y	N	Y	Y	Y	Y	No new observations
7/2/2019	6:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
7/7/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
7/15/2019	18:00	Y	N	Y	Y	Y	Y	Water samples taken -- leak detection / liner fence in good condition
7/18/2019	12:00	Y	N	Y	Y	Y	Y	No new observations

7/25/2019	11:00	Y	N	Y	Y	Y	Y	No new observations
7/31/2019	22:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
8/7/2019	6:00	Y	N	Y	Y	Y	Y	No new observations
8/12/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
8/19/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
8/24/2019	22:00	Y	N	Y	Y	Y	Y	No new observations
8/30/2019	6:00	Y	N	Y	Y	Y	Y	No new observations
9/5/2019	9:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
9/13/2019	22:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
9/17/2019	13:00	Y	N	Y	Y	Y	Y	No new observations
9/20/2019	6:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
9/29/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
10/4/2019	18:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
10/10/2019	12:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
10/18/2019	22:00	Y	N	Y	Y	Y	Y	No new observations
10/24/2019	15:00	Y	N	Y	Y	Y	Y	No new observations
10/31/2019	9:00	Y	N	Y	Y	Y	Y	No new observations
11/6/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
11/11/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
11/17/2019	19:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
11/25/2019	22:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
11/28/2019	15:00	Y	N	Y	Y	Y	Y	No new observations
12/4/2019	9:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
12/11/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
12/17/2019	18:00	Y	N	Y	Y	Y	Y	No new observations
12/24/2019	12:00	Y	N	Y	Y	Y	Y	No new observations
12/30/2019	2:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
1/5/2020	22:00	Y	N	Y	Y	Y	Y	No new observations
1/9/2020	9:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
1/14/2020	18:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
1/22/2020	12:00	Y	N	Y	Y	Y	Y	No new observations
1/28/2020	11:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
2/5/2020	22:00	Y	N	Y	Y	Y	Y	Water samples taken – leak detection / liner fence in good condition
2/12/2020	6:00	Y	N	Y	Y	Y	Y	No new observations
2/16/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
2/23/2020	12:00	Y	N	Y	Y	Y	Y	No new observations
2/29/2020	22:00	Y	N	Y	Y	Y	Y	No new observations
3/6/2020	6:00	Y	N	Y	Y	Y	Y	No new observations
3/13/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
3/20/2020	22:00	Y	N	Y	Y	Y	Y	No new observations
3/27/2020	13:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
3/31/2020	6:00	Y	N	Y	Y	Y	Y	No new observations
4/7/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
4/13/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
4/18/2020	13:00	Y	N	Y	Y	Y	Y	No new observations
4/24/2020	6:00	Y	N	Y	Y	Y	Y	No new observations
4/29/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
5/6/2020	18:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
5/11/2020	12:00	Y	N	Y	Y	Y	Y	No new observations
5/19/2020	22:00	Y	N	Y	Y	Y	Y	Site in good condition
5/23/2020	15:00	Y	N	Y	Y	Y	Y	No new observations
5/30/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
6/5/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
6/12/2020	12:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
6/17/2020	19:00	Y	N	Y	Y	Y	Y	No new observations
6/24/2020	22:00	Y	N	Y	Y	Y	Y	No new observations
6/30/2020	15:00	Y	N	Y	Y	Y	Y	No new observations
7/6/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
7/13/2020	18:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
7/20/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
7/25/2020	12:00	Y	N	Y	Y	Y	Y	No new observations
7/31/2020	2:00	Y	N	Y	Y	Y	Y	No new observations
8/7/2020	22:00	Y	N	Y	Y	Y	Y	No new observations
8/13/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
8/18/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
8/25/2020	12:00	Y	N	Y	Y	Y	Y	No new observations
8/31/2020	11:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
9/7/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
9/12/2020	12:00	Y	N	Y	Y	Y	Y	No new observations
9/19/2020	19:00	Y	N	Y	Y	Y	Y	No new observations
9/24/2020	22:00	Y	N	Y	Y	Y	Y	No new observations
9/30/2020	15:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
10/7/2020	9:00	Y	N	Y	Y	Y	Y	No new observations
10/13/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
10/18/2020	18:00	Y	N	Y	Y	Y	Y	No new observations
10/21/2020	12:00	Y	N	Y	Y	Y	Y	Site in good condition
10/30/2020	2:00	Y	N	Y	Y	Y	Y	No new observations
11/6/2020	22:00	Y	N	Y	Y	Y	Y	Leak detection / liner / fence in good condition
11/13/2020	9:00	Y	N	Y	Y	Y	Y	No new observations

[illegible]

Date	Visual inspection conducted:	Notes on Issue found (if any):
January	Y/N	
Week 1: Dec 27- Jan 2	Y	
Week 2: Jan 3-9	N	
Week 3: Jan 10-16	N	
Week 4: Jan 17-23	Y	
Week 5: Jan 24-30	Y	
February		
Week 1: Jan 31-Feb 6	Y	
Week 2: Feb 7-13	Y	
Week 3: Feb 14-20	Y	
Week 4: Feb 21-27	Y	
Week 5: Feb 28- March 6	Y	
March		
Week 1: Mar 7-13	Y	
Week 2: Mar 14-20	Y	
Week 3: Mar 21-27	Y	
Week 4: Mar 28-April 3	N	
April		
Week 1: March 29-April 4	Y	
Week 2: April 4-10	Y	
Week 3: April 11-17	N	
Week 4: April 18-24	Y	
Week 5: April 25-April 31	Y	
May		
Week 1: May 2-8	N	
Week 2: May 9-15	Y	
Week 3: May 16-22	Y	
Week 4: May 23-29	Y	
June		
Week 1: May 30-Jun 5	Y	
Week 2: June 6-12	N	
Week 3: June 13-19	Y	
Week 4: June 20-26	Y	
Week 5: June 27- Jul 3	N	
July		
Week 1: July 4-July 10	N	
Week 2: July 11-17	N	
Week 3: July 18-24	N	
Week 4: July 25-July 31	N	
August		
Week 1: Aug 1-7	N	
Week 2: Aug 8-14	N	
Week 3: Aug 15-21	Y	
Week 4: Aug 22-28	Y	
Week 5: Aug 29-Sept 4	N	
September		

Week 1:Sept 5-11	Y	
Week 2: Sept 12-18	Y	
Week 3: Sept 19-25	Y	
Week 4: Sept 26-Oct 2	Y	
October		
Week 1: Oct 3-Oct 9	Y	
Week 2: Oct 10-16	Y	
Week 3:Oct 17-23	N	
Week 4: Oct 24-30	Y	
November		
Week 1: Oct 31-Nov 6	N	
Week 2: Nov 7-13	N	
Week 3: Nov 14-20	Y	
Week 4: Nov 21- Nov 27	Y	
December		
Week 1:Nov 28-Dec 4	Y	
Week 2: Dec 5-11	N	
Week 3:Dec 12-18	N	
Week 4: Dec 19-25	Y	
Week 5: Dec 26-Jan 1	Y	

Week Starting Date	Visual inspection conducted:	Notes on Issue found (if any):
1/2/2022	Y	
1/9/2022	N	
1/16/2022	Y	
1/23/2022	Y	
1/30/2022	Y	
2/6/2022	Y	
2/13/2022	Y	
2/20/2022	Y	
2/27/2022	Y	
3/6/2022	Y	
3/13/2022	N	
3/20/2022	Y	
3/27/2022	Y	
4/3/2022	Y	
4/10/2022	Y	
4/17/2022	Y	
4/24/2022	Y	
5/1/2022	N	
5/8/2022	N	
5/15/2022	Y	
5/22/2022	Y	
5/29/2022	Y	
6/5/2022	Y	
6/12/2022	Y	
6/19/2022	N	
6/26/2022	Y	
7/3/2022	N	
7/10/2022	N	
7/17/2022	N	
7/24/2022	Y	
7/31/2022	N	
8/7/2022	N	
8/14/2022	Y	
8/21/2022	Y	
8/28/2022	N	
9/4/2022	N	
9/11/2022	N	
9/18/2022	Y	
9/25/2022	Y	
10/2/2022	N	
10/9/2022	N	
10/16/2022	Y	
10/23/2022	N	
10/30/2022	Y	
11/6/2022	Y	
11/13/2022	Y	
11/20/2022	Y	
11/27/2022	Y	
12/4/2022	Y	
12/11/2022	Y	
12/18/2022	Y	
12/25/2022	Y	

Week Starting Date	Visual inspection conducted:	Notes on Issue found (if any):
1/2/2023	Y	
1/9/2023		
1/16/2023		
1/23/2023		
1/30/2023		



P.O. Box 2267, Midland, Texas 79702
Phone: (432) 848-9133

January 11, 2022

Ms. Victoria Venegas, Environmental Specialist
EMNRD- Oil Conservation Division
506 W. Texas Artesia, NM 88210

Re: EOG Chili Pepper Pit 1RF-26

Dear Ms. Venegas:

Thank you for allowing EOG to continue to promote water reuse in the State of New Mexico for our operations. EOG (Owner/Operator), and Accelerated (operator) plan to have active completion operations near this pit location into 2024. EOG Resources Inc., would like to formally request an extension to our currently approved permit.

Sincerely,

Patricia Donald

Patricia Donald
Regulatory Specialist

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, February 4, 2021 10:46 AM
To: Jennie Kent; Bratcher, Mike, EMNRD
Cc: dustin_kinder@eogresources.com
Subject: 1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit. Extension for cessation of operations

1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit. Approval with conditions of cessation of operations extension request.

Ms. Kent,

NMOCD has reviewed the determination of cessation of operations extension request for 1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit, received from EOG RESOURCES INC [7377] on January, 13 2021. The cessation for operations extension request is approved with the following conditions of approval:

- The 1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit extension of cessation of operations is approved from January 13, 2021 through July 13, 2021.
- EOG will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. EOG may maintain a higher liquid level if they choose.
- EOG will provide written notice to the OCD at least 72 hours, but no more than one week, prior to the recommencement of operations. Recommencement of recycling operations means that the operator plans to resume moving fluids through the containment and discharging fluids from the containment.
 - At the resumption of recycling operations, EOG is required to perform an incremental fluid level test for containment liquid levels above the minimum liquid level.
 - EOG will maintain the liquid level for each 10% volume increase for 24 hours and inspect and operation the leak detection system at the end of the 24-hour period.
 - If the detected fluid is confirmed to be produced water, EOG must comply with 19.15.34.13 NMAC.
 - EOG must submit copies of the detailed containment inspection records for the prior three (3) months and a report detailing the incremental fluid level test process and results to through the [OCD Online](#) system using a C-147. If the recommencement of operations will affect the operating and maintenance plan or closure plan, operators should check those boxes in section 9 and provide updated plans or plan addendums as attachments to the C-147.
- EOG will continue to operate, maintain, and close the 1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit in compliance with 19.15.34 NMAC, to include but not limited detailed inspection records, removal of trash/oil from containment, and monthly C-148 reporting (even if there is zero activity).
- Water reuse and recycling from 1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit is limited to wells owned or operated by EOG RESOURCES INC [7377].
- EOG may request a variance for an additional extension to the determination of cessation of operations. Extensions are considered for a maximum length of six months. Additional requests must be submitted through the [OCD Online](#) on a Form C-147L as an Extension request and should include a variance request and summary per 19.15.34.16 NMAC and the detailed inspection records for the prior three months.

The signed C-147 can be found on the OCD website at:

<https://ocdimage.emnrd.state.nm.us/imaging/AEOrderFileView.aspx?appNo=pOY1805031799>

Please do not hesitate to contact me if you have any questions or comments

Victoria Venegas • Environmental Specialist
Environmental Bureau

EMNRD - Oil Conservation Division
811S. First St. | Artesia, NM 88210
(575) 909-0269 | Victoria.Venegas@state.nm.us
<http://www.emnrd.state.nm.us/OCD/>



District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 175177

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 175177
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 1RF-26 - Chili Pepper Water Recycling Facility and Containment Pit Facility ID [fOY1805031625] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of January 16, 2023. The new registration/permit expiration date is January 16, 2024. • If EOG RESOURCES INC [7377] wishes to extend the registration/permit past January 16, 2024, a registration/permit extension request must be submitted to OCD. The extension request should be submitted no later than December 16, 2023.	1/12/2023