

Javelina Unit P429 (429H, 430H, 431H, 432H) Facility ID fVV2214455406 (Daily drilling inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	ence maintair	NOTES
2/19/2024	Good	>3.0'	Good	None	None	None	Good	Checked during initial mobilization to pad
2/20/2024	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
2/21/2024	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
2/22/2024	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
2/23/2024	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
2/24/2024	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
2/25/2024	Good	>3.0'	Good	None	None	None	Good	DSR visual daily inspection
2/26/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
2/27/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
2/28/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
2/29/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
3/1/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
3/2/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
3/3/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
3/4/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
3/5/2024	Good	>4.0'	Good	None	None	None	Good	DSR visual daily inspection
3/6/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/7/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/8/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/9/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/10/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/11/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/12/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/13/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/14/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/15/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/16/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/17/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/18/2024	Good	>4.5'	Good	None	None	None	Good	DSR visual daily inspection
3/19/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/20/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/21/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/22/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/23/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/24/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/25/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/26/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/27/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/28/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/29/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/30/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
3/31/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/1/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/2/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/3/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/4/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/5/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/6/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/7/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/8/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/9/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/10/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/11/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/12/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/13/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/14/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/15/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/16/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/17/2024	Good	>5.0'	Good	None	None	None	Good	DSR visual daily inspection
4/18/2024	Good	>6.0'	Good	None	None	None	Good	DSR visual daily inspection
4/19/2024	Good	>6.0'	Good	None	None	None	Good	DSR visual daily inspection
4/20/2024	Good	>6.0'	Good	None	None	None	Good	DSR visual daily inspection
4/21/2024	Good	>6.0'	Good	None	None	None	Good	DSR visual daily inspection
4/22/2024	Good	>6.0'	Good	None	None	None	Good	Final inspection after rig mobilization from pad

Released to Imaging: 5/23/2024 8:56:47 AM

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 346589

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 346589
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	5/23/2024