

JAVELINA UNIT Pad 610 (507H, 508H, 610H, 611H, 612H) Facility ID - fJMB2221536628 (Weekly inspection log)								
INSPECTION DATE	Liner integrity	Freeboard Height - Maintain at least 2ft	Fluid levels	Debris	Migratory birds / wildlife	Releases	Is fence maintained	NOTES
6/5/2024	GOOD	YES	<1"	X	NO	NO	YES	no issues to report
6/12/2024	GOOD	YES	<1"	X	NO	NO	YES	no issues to report
6/19/2024	GOOD	YES	<1"	X	NO	NO	YES	no issues to report
6/26/2024	GOOD	YES	<1"	X	NO	NO	YES	no issues to report
7/3/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
7/10/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
7/17/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
7/24/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
7/31/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
8/7/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
8/14/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
8/21/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
8/28/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
9/4/2024	GOOD	YES	<1"	x	NO	NO	YES	no issues to report
9/9/2024	GOOD	YES	<1"	x	NO	NO	YES	pit closure started

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 389692

CONDITIONS

Operator: CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID: 4323
	Action Number: 389692
	Action Type: [C-144] Temporary Pit Plan (C-144T)

CONDITIONS

Created By	Condition	Condition Date
joseph.kennedy	None	10/8/2024